

SERVICE BULLETIN

AFTERSALES SERVICE OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CORRECTION	ISSUE NO. : MSB-08E23-502	DATE : 2008-02-05
SUBJECT : A/T FLUID TEMPERATURE SENSOR CHECK	<div> <div><MODEL></div> <div>(EUR)</div> <div>OUTLANDER</div> <div>(GS45X)(CW0W)</div> </div> <div> <div><M/Y></div> <div>07-</div> </div>	
GROUP : AUTOMATIC TRANSMISSION		

1. Description:


The A/T fluid temperature sensor check is corrected in the applicable Workshop Manuals. This Service Bulletin contains the modified descriptions.

2. Applicable Manuals:

Manual	Pub. No.	Title (Info-ID)	Attachment
2007 OUTLANDER Workshop Manual	CGXE07E1-CD (English) CGXS07E1-CD (Spanish) CGXF07E1-CD (French) CGXG07E1-CD (German)	A/T Fluid Temperature Sensor Check (M231-00-450-40700-01)	Attachment 1
2008 OUTLANDER Workshop Manual	CGXE08E2-CD (English) CGXS08E2-CD (Spanish) CGXF08E2-CD (French) CGXG08E2-CD (German)	A/T Fluid Temperature Sensor Check (M231-00-450-45200-01)	Attachment 1

3. Corrected Specifications:

See Attachment 1.



A/T FLUID TEMPERATURE SENSOR CHECK

1. Disconnect the A/T control solenoid valve assembly connector. **and No. 3 <Added>**
2. Measure the resistance between the sensor-side connector terminal No. 2 of the A/T control solenoid valve assembly connector **and the earth.**

Standard value: **<Deleted>**

Fluid temperature °C	Resistance kΩ
10	Approx. 6.62
25	Approx. 3.51
80	Approx. 0.55
110	Approx. 0.25

NOTE: In the information screen on the multi-information display, the fluid temperature warning comes on when the A/T fluid temperature is approximately 140 °C or higher, and automatically goes out when the A/T fluid temperature dropped below approximately 135 °C.

CAUTION

The A/T fluid temperature sensor cannot be removed or replaced as a single unit. When the A/T fluid temperature sensor needs to be replaced, replace the valve body assembly.

3. When the resistance of the A/T fluid temperature sensor is outside the standard value, and the fluid temperature warning comes on/goes out at other than the specified temperatures, replace the valve body assembly and the harness.