

SERVICE BULLETIN

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE: CORRECTION	ISSUE NO.: MSB-10E13-503	DATE: 2010-09-05	
SUBJECT : RESISTANCE OF	<model></model>	<m y=""></m>	
GROUP : FUEL		(EUR/RUSSIA) OUTLANDER (CW0W)	10—11

1. Description:

In STEP 2 of the diagnosis procedures for diagnosis codes P2100 and P2101, the unit of resistance for the throttle valve control servo has been incorrect. This Service Bulletin contains the correct information.

 $\begin{array}{cccc} \text{<Correct>} & & \text{<Incorrect>} \\ \Omega & \leftarrow & k\Omega \end{array}$

2. Applicable Manuals:

<EUR>

Manual	Pub. No.	Engine	Title (Info-ID)	Attached Sheet
2010 OUTLANDER Workshop Manual	CGXE10E1-CD (English) CGXF10E1-CD (French) CGXG10E1-CD (German) CGXS10E1-CD (Spanish) CGXI10E1-CD (Italian)	4B12	P2100: Throttle Valve Control Servo Circuit (open) (M131-76-150-50300-01)	Attached sheet A
			P2101: Throttle Valve Control Servo Magneto Malfunction (M131-76-160-56600-01)	Attached sheet B
Workshop Manual CGXF11E1- CGXG11E1- CGXS11E1-	CGXE11E1-CD (English) CGXF11E1-CD (French) CGXG11E1-CD (German) CGXS11E1-CD (Spanish) CGXI11E1-CD (Italian)	4B12	P2100: Throttle Valve Control Servo Circuit (open) (M131-76-151-07800-01)	Attached sheet A
			P2101: Throttle Valve Control Servo Magneto Malfunction (M131-76-160-89000-01)	Attached sheet B

<RUSSIA>

Underneath Manual	Underneath Pub. No.	Engine	Title (Info-ID)	Attached Sheet
2010 OUTLANDER Workshop Manual	N/A	4B12	P2100: Throttle Valve Control Servo Circuit (open) (M131-76-150-50300-01)	Attached sheet A
			P2101: Throttle Valve Control Servo Magneto Malfunction (M131-76-160-56600-01)	Attached sheet B
2011 OUTLANDER Workshop Manual	N/A	4B12	P2100: Throttle Valve Control Servo Circuit (open) (M131-76-151-07800-01)	Attached sheet A
			P2101: Throttle Valve Control Servo Magneto Malfunction (M131-76-160-89000-01)	Attached sheet B

There may be some attached sheets not included in this Service Bulletin because they are not applicable to your market. Their sheet numbers are not listed in the above table.

1

3. Corrected Specifications:

See Attached sheets A and B.

TROUBLE JUDGMENT

Check Conditions

- Battery positive voltage is more than 8.3 V.
- Difference between the throttle position sensor (main) output voltage and the target throttle position sensor (main) voltage is more than 0.1 V.
- Difference between the throttle position sensor (sub) output voltage and the target throttle position sensor (sub) voltage is more than 0.1 V.
- The drive duty of the throttle valve control servo is more than 100 %.
- Except while engine is being cranked.

or

- Battery positive voltage is more than 8.3 V.
- Difference between the target throttle position sensor (main) voltage and the throttle position sensor (main) output voltage is more than 0.1 V.
- Difference between the target throttle position sensor (sub) voltage and the throttle position

sensor (sub) output voltage is more than 0.1 V.

- The drive duty of the throttle valve control servo is more than 100 %.
- Except while engine is being cranked.

Judgement Criterion

 Difference between the throttle position sensor (main) output voltage and the learning value of the middle-opened degree is less than 0.2 V.

or

 Difference between the throttle position sensor (sub) output voltage and the learning value of the middle-opened degree is less than 0.2 V.

PROBABLE CAUSES

- Failed throttle valve control servo.
- Short circuit or harness damage in throttle valve control servo circuit or lose connector contact.
- Failed engine-ECU

DIAGNOSIS PROCEDURE


STEP 1. Connector check: B-20 electronic-controlled throttle valve connector

Q: Is the check result normal?

YES: Go to Step 2.

NO: Repair or replace the connector.

STEP 2. Perform resistance measurement at B-20 electronic-controlled throttle valve connector.



Resistance between terminal No. 1 and No. 2.

OK: 0.3 – 100 (at 20 °C)

Q: Is the check result normal?

YES: Go to Step 3.

NO: Replace the throttle body assembly.

STEP 3. Connector check: B-30 engine-ECU connector

Q: Is the check result normal?

YES: Go to Step 4.

NO: Repair or replace the connector.



TROUBLE JUDGMENT

Check Condition

• Battery positive voltage is higher than 8.3 V.

Judgement Criterion

 The coil current of the throttle actuator control motor is 8 A or more.

<Correct> Ω

PROBABLE CAUSES

- Failed throttle valve control servo.
- Short circuit or harness damage in throttle valve control servo circuit or lose connector contact.
- Failed engine-ECU

DIAGNOSIS PROCEDURE

STEP 1. Connector check: B-20 electronic-controlled throttle valve connector

Q: Is the check result normal?

YES: Go to Step 2.

NO: Repair or replace the connector.

STEP 2. Perform resistance measurement at B-20 electronic-controlled throttle valve connector.

- Disconnect connector, and measure at electronic-controlled throttle valve side. < Incorrect>
- Resistance between terminal No. 1 and No. 2.

OK: 0.3 – 100 (at 20 °C)

Q: Is the check result normal?

YES: Go to Step 3.

NO: Replace the throttle body assembly.

STEP 3. Connector check: B-29 engine-ECU connector

Q: Is the check result normal?

YES: Go to Step 4.

NO: Repair or replace the connector.

STEP 4. Check harness between B-20 (terminal No. 1) electronic-controlled throttle valve connector and B-29 (terminal No. 15) engine-ECU connector.

Check output line for short circuit and damage.

Q: Is the check result normal?

YES: Go to Step 5.

NO: Repair the damaged harness wire.

STEP 5. Check harness between B-20 (terminal No. 2) electronic-controlled throttle valve connector and B-29 (terminal No. 16) engine-ECU connector.

• Check output line for short circuit and damage.

Q: Is the check result normal?

YES: Go to Step 6.

NO: Repair the damaged harness wire.

