

SERVICE BULLETIN

DOMESTIC SALES & AFTER SALES SERVICE OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE: INFORMATION	ISSUE NO.: MSB-10E00-005	DATE: 2010-05-20	
SUBJECT : ROOF PANEL		<model> (EUR/RUSSIA)</model>	<m y=""> 07, 08</m>
GROUP : GENERAL		OUTLANDER (CW0W)	07,00

1. Description:

The service part roof panel and the front roof rail formerly supplied as subassembly are changed to be supplied separately. Due to this change, some welding points are added to the roof panel repair procedure. This Service Bulletin contains the detailed information regarding these additional welding points.

2. Applicable Manuals:

<EUR>

Manual	Pub. No.	Title (Info-ID)	Attached Sheet
2007 OUTLANDER Workshop Manual	CGXE07E1-CD (English) CGXS07E1-CD (Spanish) CGXF07E1-CD (French) CGXG07E1-CD (German)	Roof (Aluminium Roof) (M030-00-270-06500-01)	Attached sheet 4
2008 OUTLANDER Workshop Manual	CGXE08E2-CD (English) CGXS08E2-CD (Spanish) CGXF08E2-CD (French) CGXG08E2-CD (German)	Roof (Aluminium Roof) (M030-00-270-11700-01)	

<RUSSIA>

Underneath Manual	Underneath Pub. No.	Title (Info-ID)	Attached Sheet
2007 OUTLANDER Workshop Manual	N/A	Roof (Aluminium Roof) (M030-00-270-06500-01)	Attached sheet 4
2008 OUTLANDER Workshop Manual	N/A	Roof (Aluminium Roof) (M030-00-270-11700-01)	

There may be some attached sheets not included in this Service Bulletin because they are not applicable to your market. Their sheet numbers are not listed in the above table.

3. Details:

See Attached sheet 4.

REPAIR WELDS

MSB-10E00-005 (10RV010)2

