



SERVICE BULLETIN

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : CORRECTION	ISSUE NO. : MSB-12E54-503B	DATE : 2012-06-27
SUBJECT : LIN TROUBLE SHOOTING		<MODEL> <M/Y> (EUR/RUSSIA)
GROUP : CHASSIS ELECTRICAL		ALL VEHICLE WITH LIN

1. Description:

An incorrect description about the diagnosis codes U1515 and U1570 regarding LIN have been found in the applicable Service Manual. This contains the corrected information.

2. Applicable Manual :
See the attached 2

3. Details:
See Attached sheet 4

EXCEPT JAPAN**DELICA D:5**

<G. EXP-JAPAN SPEC>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2007 DELICA D:5 Workshop Manual	PWRE0711R	Code No.U1515 No-Bus activity error (LIN) (M545-10-170-08300-01)	Attached sheet 4
2009 DELICA D:5 Workshop Manual	PWRE0804R	Code No.U1515 No-Bus activity error (LIN) (M545-10-170-08301-01)	
2011 DELICA D:5 Workshop Manual	SERVICE BULLETIN MSB-10X00-025	Code No.U1515 No-Bus activity error (LIN) (M545-10-170-83400-01)	

LANCER/LANCER EX

<G. EXP/GCC/CHINA/MMAL/NEW ZEALAND/ARGENTINA/SOUTH AFRICA/HONG KONG>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2008 LANCER/LANCER EX Workshop Manual (G. EXP/GCC/ARGENTINA /SOUTH AFRICA)	PWME0701R(English) PWMS0702R(Spanish) ARGENTINA/SOUTH AFRICA:DRAFT	Code No.U1515 No-Bus activity error (LIN) <vehicles for General Export and GCC> (M545-10-170-09400-01) Code No.U1515 No-Bus activity error (LIN) <vehicles for South Africa> (M545-10-170-10200-01) Code No.U1515 No-Bus activity error (LIN) <vehicles for Argentina> (M545-10-170-11300-01)	Attached sheet 4
2008 LANCER Workshop Manual (MMAL/NEW ZEALAND)	MMAL:MR936470 MMNZ:DRAFT	Code No.U1515 No-Bus activity error (LIN) (M545-10-170-17900-01)	
2009 LANCER Workshop Manual (MMAL/NEW ZEALAND)	MMAL:MR936503 MMNZ:DRAFT	Code No.U1515 No-Bus activity error (LIN) (M545-10-170-38400-01)	
2009 LANCER Workshop Manual (CHINA)	CHINA:DRAFT	Code No.U1515 No-Bus activity error (LIN) (M545-10-170-43600-01)	
2009 LANCER/LANCER EX Workshop Manual (G. EXP/GCC/ARGENTINA /SOUTH AFRICA/ HONG KONG)	PWME0802R(English) PWMS0803R(Spanish) ARGENTINA/SOUTH AFRICA/HONG KONG:DRAFT	Code No.U1515 No-Bus activity error (LIN) <vehicles for General Export and GCC> (M545-10-170-33900-01) Code No.U1515 No-Bus activity error (LIN) <vehicles for South Africa> (M545-10-170-34000-01)	
2010 LANCER/LANCER EX Workshop Manual (G. EXP/GCC/ARGENTINA /SOUTH AFRICA/ HONG KONG)	PWME0901R(English) PWMS0902R(Spanish) ARGENTINA/SOUTH AFRICA/HONG KONG:DRAFT	Code No.U1515 No-Bus activity error (LIN) <vehicles for Argentina> (M545-10-170-35100-01) Code No.U1515 No-Bus activity error (LIN) <vehicles for Hong Kong> (M545-10-170-32800-01)	
2010 LANCER Workshop Manual (CHINA)	PWME0901R(Eng) PWMS0902R(Spa) MMAL/NZ:DRAFT	Code No.U1515 No-Bus activity error (LIN) (M545-10-170-57700-01)	
2010 LANCER Workshop Manual (MMAL/NEW ZEALAND)	CHINA:DRAFT	Code No.U1515 No-Bus activity error (LIN) (M545-10-170-38401-01) 	

2011 LANCER/LANCER EX Workshop Manual (G. EXP/GCC/ARGENTINA/SOUTH AFRICA/HONG KONG)	PWME1010R(Eng) PWMS1011R(Spa) ARGENTINA/SOUTH AFRICA/HONG KONG:DRAFT MMAL/NZ:DRAFT	Code No.U1515 No-Bus activity error(LIN) <vehicles for General Export and GCC> (M545-10-170-72600-01) Code No.U1515 No-Bus activity error(LIN) <vehicles for South Africa> (M545-10-170-73700-01) Code No.U1515 No-Bus activity error(LIN) <vehicles for Argentina> (M545-10-170-74800-01) Code No.U1515 No-Bus activity error(LIN) <vehicles for Hong Kong> (M545-10-170-75900-01)	Attached sheet 4
2011 LANCER Workshop Manual (MMAL/NEW ZEALAND)		Code No.U1515 No-Bus activity error(LIN) (M545-10-170-77100-01)	

<THAILAND>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2009 LANCER Workshop Manual	DRAFT	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-56600-01)	Attached sheet 4
2010 LANCER Workshop Manual		Code No.U1515 No-Bus activity error(LIN) (M545-10-170-94200-01)	
2011 LANCER Workshop Manual		Code No.U1515 No-Bus activity error(LIN) (M545-10-170-96400-01)	

<EU/RUSSIA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2008 LANCER Workshop Manual (EU)	CG1E08E1-CD(English) CG1S08E1-CD(Spanish) CG1F08E1-CD(French) CG1G08E1-CD(German)	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-13500-01)	Attached sheet 4
2008 LANCER Workshop Manual (RUSSIA)	N/A	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-12401-01)	
2008 LANCER Workshop Manual (EU/RUSSIA)	CG1E08E2-CD(English) CG1S08E2-CD(Spanish) CG1F08E2-CD(French) CG1G08E2-CD(German) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-24300-01)	
2009 LANCER Workshop Manual (EU/RUSSIA)	CG1E09E1-CD(English) CG1S09E1-CD(Spanish) CG1F09E1-CD(French) CG1G09E1-CD(German) CG1I09E1-CD(Italy) RUSSIA:N/A		
2010 LANCER Workshop Manual (EU/RUSSIA)	CG1E10E1-CD(English) CG1S10E1-CD(Spanish) CG1F10E1-CD(French) CG1G10E1-CD(German) CG1I10E1-CD(Italy) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-48100-01)	

<MMNA/KOREA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2008 LANCER Service Manual (MMNA)	MSCD-106B-2008	DTC U1515: No-Bus activity error(LIN) (M545-10-170-07201-01)	Attached sheet 5
2009 LANCER Service Manual (MMNA)	MSCD-106B-2009	DTC U1515: No-Bus activity error(LIN) (M545-10-170-26500-01)	

2009+2009.5 LANCER Service Manual (MMNA)	MSCD-106B-2009.5	DTC U1515: No-Bus activity error(LIN) (M545-10-170-39501-01)	
2010 LANCER Service Manual (MMNA)	MSCD-106B-2010		
2011 LANCER Service Manual (KOREA)	DRAFT	DTC U1515: No-Bus activity error(LIN) (M545-10-170-93100-01)	

LANCER SPORTBACK

<MMAL/NEW ZEALAND>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2009 LANCER SPORTBACK Workshop Manual	MMAL:MR936570 MMNZ:DRAFT	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-45800-01)	Attached sheet 4
2010 LANCER SPORTBACK Workshop Manual	MMAL/NZ DRAFT	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-45801-01)	
2011 LANCER SPORTBACK Workshop Manual	MMAL/NZ:DRAFT	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-84500-01)	

<EU/RUSSIA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2009 LANCER SPORTBACK Workshop Manual	CG4E09E1-CD(English) CG4S09E1-CD(Spanish) CG4F09E1-CD(French) CG4G09E1-CD(German) CG4I09E1-CD(Italy) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-37300-01)	Attached sheet 4
2010 LANCER SPORTBACK Workshop Manual	CG4E10E1-CD(English) CG4S10E1-CD(Spanish) CG4F10E1-CD(French) CG4G10E1-CD(German) CG4I10E1-CD(Italy) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-37301-01)	

<MMNA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2009 LANCER SPORTBACK Service Manual	MSCD-214B-2009	DTC U1515: No-Bus activity error(LIN) (M545-10-170-47001-01)	Attached sheet 5
2010 LANCER SPORTBACK Service Manual	MSCD-214B-2010		

LANCER/LANCER SPORTBACK

<EU/RUSSIA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2011 LANCER/LANCER SPORTBACK Workshop Manual	CG1E11E1-CD(English) CG1S11E1-CD(Spanish) CG1F11E1-CD(French) CG1G11E1-CD(German) CG1I11E1-CD(Italy) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-65200-01)	Attached sheet 4
2012 LANCER/LANCER SPORTBACK Workshop Manual	CG1E12E1-CD(English) CG1S12E1-CD(Spanish) CG1F12E1-CD(French) CG1G12E1-CD(German) CG1I12E1-CD(Italy) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-97500-01)	

<MMNA/MEXICO>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2011 LANCER/LANCER SPORTBACK Service Manual	MSCD-106B-2011 MEXICO:DRAFT	DTC U1515: No-Bus activity error(LIN) (M545-10-170-70400-01)	Attached sheet 5
2012 LANCER/LANCER SPORTBACK Service Manual	MSCD-106B-2012 MEXICO:DRAFT	DTC U1515: No-Bus activity error(LIN) (M545-10-171-01900-01)	

LANCER EVOLUTION

<EU/MMAL/NEW ZEALAND/G. EXP/CHINA/GCC/RUSSIA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2008 LANCER EVOLUTION Workshop Manual (EU)	N/A(Only for UK)	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-19100-01)	Attached sheet 4
2009 LANCER EVOLUTION Workshop Manual (EUR/MMAL/NEW ZEALAND)	CGEE09E1-CD(Eng) CGES09E1-CD(Spa) CGEF09E1-CD(Fre) CGEG09E1-CD(Ger) CGEI09E1-CD(Ita) MMAL:MR936442 MMNZ:DRAFT	Code No.U1515 No-Bus activity error(LIN) <Vehicles for Europe> (M545-10-170-28700-01) Code No.U1515 No-Bus activity error(LIN) <Vehicles for Australia and New Zealand> (M545-10-170-29800-01)	
2009 LANCER EVOLUTION Workshop Manual (EU/MMAL/NEW ZEALAND/G. EXP)	CGEE09E1-CD(English) CGES09E1-CD(Spanish) CGEF09E1-CD(French) CGEG09E1-CD(German) CGEI09E1-CD(Italy) MMAL:MR936442 MMNZ:DRAFT	Code No.U1515 No-Bus activity error(LIN) <Vehicles for Europe> (M545-10-170-28700-01) Code No.U1515 No-Bus activity error(LIN) <Vehicles for Australia and New Zealand> (M545-10-170-29800-01) Code No.U1515 No-Bus activity error(LIN) <RS> (M545-10-170-31700-01)	
2009 LANCER EVOLUTION Workshop Manual (EU/MMAL/NEW ZEALAND/CHINA/GCC/G. EXP)	CGEE09E1-CD(English) CGES09E1-CD(Spanish) CGEF09E1-CD(French) CGEG09E1-CD(German) CGEI09E1-CD(Italy) G. EXP/GCC PWSE0801R-A MMAL:MR936442 MMNZ:DRAFT	Code No.U1515 No-Bus activity error(LIN) <Vehicles for Europe, GCC and China> (M545-10-170-41400-01) Code No.U1515 No-Bus activity error(LIN) <Vehicles for Australia and New Zealand> (M545-10-170-29801-01) Code No.U1515 No-Bus activity error(LIN) <RS> (M545-10-170-31700-01)	
2010 LANCER EVOLUTION Workshop Manual (EU/G. EXP)	CGEE10E1-CD(Eng) CGES10E1-CD(Spa) CGEF10E1-CD(Fre) CGEG10E1-CD(Ger) CGEI10E1-CD(Ita) G. EXP:PWSE0905R	Code No.U1515 No-Bus activity error(LIN) <Vehicles for Europe> (M545-10-170-52200-01) Code No.U1515 No-Bus activity error(LIN) <RS> (M545-10-170-53300-01)	
2010 LANCER EVOLUTION Workshop Manual (CHINA/GCC/MMAL/NEW ZEALAND/G. EXP)	G. EXP/GCC:PWSE0905R CHINA:DRAFT MMAL:DRAFT MMNZ:DRAFT CHINA:DRAFT	Code No.U1515 No-Bus activity error(LIN) <Vehicles for Australia and New Zealand> (M545-10-170-29802-01) Code No.U1515 No-Bus activity error(LIN) <RS> (M545-10-170-31701-01)	
2011 LANCER EVOLUTION Workshop Manual (EU/RUSSIA/G. EXP)	CGEE11E1-CD(Eng) CGES11E1-CD(Spa) CGEF11E1-CD(Fre) CGEG11E1-CD(Ger) CGEI11E1-CD(Ita) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) <Vehicles for Europe> (M545-10-170-78200-01) Code No.U1515 No-Bus activity error(LIN) <RS> (M545-10-170-79300-01)	

2011 LANCER EVOLUTION Workshop Manual (INDIA/GCC/MMAL/NEW ZEALAND/G. EXP)	G. EXP/GCC/INDIA:PWSE1008R MMALDRAFT MMNZ:DRAFT	Code No.U1515 No-Bus activity error(LIN) <RS> (M545-10-170-80100-01) Code No.U1515 No-Bus activity error(LIN) <Except RS> (M545-10-170-81200-01)	
2012 LANCER EVOLUTION Workshop Manual (EU/RUSSIA/G. EXP)	G. EXP:PWSE1113R CGEE12E1-CD(Eng) CGES12E1-CD(Spa) CGEF12E1-CD(Fre) CGEG12E1-CD(Ger) CGEI12E1-CD(Ita) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) <Vehicles for Europe> (M545-10-170-98600-01) Code No.U1515 No-Bus activity error(LIN) <RS> (M545-10-170-99700-01)	

<MMNA/KOREA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2008 LANCER EVOLUTION Service Manual (MMNA)	MSCD-206B-2008	DTC U1515: No-Bus activity error(LIN) (M545-10-170-22101-01)	Attached sheet 5
2009 LANCER EVOLUTION Service Manual (MMNA)	MSCD-206B-2009		
2010 LANCER EVOLUTION Service Manual (MMNA)	MSCD-206B-2010		
2011 LANCER EVOLUTION Service Manual (MMNA)	MSCD-206B-2011	DTC U1515: No-Bus activity error(LIN) (M545-10-170-86700-01)	
2011 LANCER EVOLUTION Service Manual (KOREA)	DRAFT	DTC U1515: No-Bus activity error(LIN) (M545-10-170-92000-01)	
2012 LANCER EVOLUTION Service Manual (MMNA)	MSCD-206B-2012	DTC U1515: No-Bus activity error(LIN) (M545-10-171-02000-01)	

OUTLANDER

<G. EXP/GCC/CHINA/MMAL/NEW ZEALAND/BRAZIL/TAIWAN/ARGENTINA/SOUTH AFRICA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2006 OUTLANDER Workshop Manual (G. EXP-JAPAN SPEC)	PWRE0503R(English)	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-01600-01)	Attached sheet 4
2007 OUTLANDER Workshop Manual (MMAL)	MR936083	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-04900-01)	
2007 OUTLANDER Workshop Manual (G. EXP/MMAL/NEW ZEALAND/CHINA)	PWRE0607R(Eng) MMAL:MR936083 MMNZ:DRAFT CHINA:DRAFT	Code No.U1515 No-Bus activity error(LIN) <LHD> (M545-10-170-05000-01) Code No.U1515 No-Bus activity error(LIN) <RHD>	
2008 OUTLANDER Workshop Manual (G. EXP/GCC)	PWRE0707R(English) PWRS0708R(Spanish)	(M545-10-170-06100-01)	
2008 OUTLANDER Workshop Manual (G. EXP-JAPAN SPEC)	PWRE712R	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-27600-01)	
2008 OUTLANDER Workshop Manual (MMAL/NEW ZEALAND/CHINA)	MMAL:MR936474 MMNZ/CHINA:DRAFT	Code No.U1515 No-Bus activity error(LIN) <LHD> (M545-10-170-20900-01) Code No.U1515 No-Bus activity error(LIN) <RHD> (M545-10-170-21000-01)	
2009 OUTLANDER Workshop Manual (G. EXP/GCC/MMAL/NEW ZEALAND)	PWRE0810R(Eng) PWRS0811R(Spa) MMAL:MR93677 MMNZ:DRAFT	Code No.U1515 No-Bus activity error(LIN) <LHD> (M545-10-170-20901-01) Code No.U1515 No-Bus activity error(LIN) <RHD> (M545-10-170-21001-01)	
2010 OUTLANDER Workshop Manual (G. EXP/CHINA/GCC/MMAL)	PWRE0906R(Eng) PWRS0907R(Spa) CHINA/MMAL:DRAFT	Code No.U1515 No-Bus activity error(LIN) <LHD> (M545-10-170-49200-01) Code No.U1515 No-Bus activity error(LIN) <RHD> (M545-10-170-50000-01)	

2011 OUTLANDER Workshop Manual (G. EXP-JAPAN SPEC)	PWRE1012R(Eng) PWRS1013R(Spa)	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-95300-01)	
2011 OUTLANDER Workshop Manual (G. EXP/GCC/CHINA/MMAL /NEW ZEALAND)	PWRE1012R(Eng) PWRS1013R(Spa) CHINA:DRAFT MMAL/MMNZ:DRAFT	Code No.U1515 No-Bus activity error(LIN) △ <LHD> (M545-10-170-71500-01)	

<INDIA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2009 OUTLANDER Workshop Manual	DRAFT	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-44700-01)	Attached sheet 4

<EU/RUSSIA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2007 OUTLANDER Workshop Manual	CGXE07E1-CD(English) CGXS07E1-CD(Spanish) CGXF07E1-CD(French) CGXG07E1-CD(German) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-03800-01) △ B	Attached sheet 4
2008 OUTLANDER Workshop Manual	CGXE08E2-CD(English) CGXS08E2-CD(Spanish) CGXF08E2-CD(French) CGXG08E2-CD(German) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) <Vehicles without lighting control sensor> (M545-10-170-16800-01) Code No.U1515 No-Bus activity error(LIN) <Vehicles with lighting control sensor> (M545-10-170-15700-01)	
2009 OUTLANDER Workshop Manual	CGXE09E1-CD(English) CGXS09E1-CD(Spanish) CGXF09E1-CD(French) CGXG09E1-CD(German) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-36200-01)	
2010 OUTLANDER Workshop Manual	CGXE10E1-CD(English) CGXS10E1-CD(Spanish) CGXF10E1-CD(French) CGXG10E1-CD(German) CGXI10E1-CD(Italy) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-51100-01)	
2011 OUTLANDER Workshop Manual	CGXE11E1-CD(Eng) CGXS11E1-CD(Spa) CGXF11E1-CD(Fre) CGXG11E1-CD(Ger) CGXI11E1-CD(Ita) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-76000-01)	
2012 OUTLANDER Workshop Manual	CGXE12E1-CD(Eng) CGXS12E1-CD(Spa) CGXF12E1-CD(Fre) CGXG12E1-CD(Ger) CGXI12E1-CD(Ita) RUSSIA:N/A		

<EU (PEUGEOT/CITROEN) >

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2008 4007/C-CROSSER WORKSHOP MANUAL	N/A	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-03801-01)	Attached sheet 4
2009 4007/C-CROSSER WORKSHOP MANUAL		Code No.U1515 No-Bus activity error(LIN) (M545-10-170-42500-01)	
2010 4007/C-CROSSER WORKSHOP MANUAL		Code No.U1515 No-Bus activity error(LIN) (M545-10-170-54400-01)	

<MMNA/KOREA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2007 OUTLANDER Service Manual (MMNA)	MSCD-007B-2007	DTC U1515: No-Bus activity error(LIN) (M545-10-170-14600-01)	Attached sheet 5
2008 OUTLANDER Service Manual (MMNA)	MSCD-007B-2008	DTC U1515: No-Bus activity error(LIN) (M545-10-170-25400-01)	
2009 OUTLANDER Service Manual (MMNA)	MSCD-007B-2009	DTC U1515: No-Bus activity error(LIN) (M545-10-170-40300-01)	
2010 OUTLANDER Service Manual (MMNA)	MSCD-007B-2010	DTC U1515: No-Bus activity error(LIN) (M545-10-170-55500-01)	
2010 OUTLANDER Service Manual (KOREA)	DRAFT	DTC U1515: No-Bus activity error(LIN) (M545-10-170-58800-01)	
2011 OUTLANDER Service Manual (MMNA)	MSCD-007B-2011	DTC U1515: No-Bus activity error(LIN) (M545-10-170-89000-01)	
2012 OUTLANDER Service Manual (MMNA)	MSCD-007B-2012		

ASX/OUTLANDER SPORT/RVR

<EU/RUSSIA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2011 ASX Workshop Manual	CGWE11E2-CD(English) CGWE11S2-CD(Spanish) CGWE11F2-CD(French) CGWE11G2-CD(German) CGWE11I2-CD(Italy) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-64101-01)	Attached sheet 4
2012 ASX Workshop Manual	CGWE12E2-CD(English) CGWE12S2-CD(Spanish) CGWE12F2-CD(French) CGWE12G2-CD(German) CGWE12I2-CD(Italy) RUSSIA:N/A	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-64100-01)	

<G. EXP/GCC/MMAL/NEW ZEALAND>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2011 ASX Workshop Manual	PWRE1006R(English) PWRS1007R(Spanish) MMAL/NZ:DRAFT	Code No.U1515 No-Bus activity error(LIN) (M545-10-170-64100-01)	Attached sheet 4

<MMNA/CANADA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2011 OUTLANDER SPORT/RVR Service Manual	MSCD-017B-2011	DTC U1515: No-Bus activity error(LIN) (M545-10-170-90800-01)	Attached sheet 5
2012 OUTLANDER SPORT/RVR Service Manual	MSCD-017B-2012		

i/i-MiEV

<EU>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2011 i-MiEV Workshop Manual	CHAE11E1-CD(English) CHAS11E1-CD(Spanish) CHAF11E1-CD(French) CHAG11E1-CD(German) CHAI11E1-CD(Italy)	Code No.U1570 No-Bus activity error(LIN) (M545-10-540-23300-01)	Attached sheet 4
2012 TQ-MiEV Workshop Manual	CHAE12E1-CD(English) CHAS12E1-CD(Spanish) CHAF12E1-CD(French) CHAG12E1-CD(German) CHAI12E1-CD(Italy)		

<G. EXP-JAPAN SPEC/MMAL/NEW ZEALAND>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2011 i Workshop Manual (G. EXP-JAPAN SPEC)	DRAFT	Code No.U1570 No-Bus activity error(LIN) (M545-10-540-34100-01)	Attached sheet 4
2012 i-MiEV Workshop Manual (MMAL/NEW ZEALAND)	DRAFT	Code No.U1570 No-Bus activity error(LIN) (M545-10-540-36300-01)	

<MMNA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2012 i-MiEV Service Manual	MSCD-018B-2012	 DTC U1570: No-Bus activity error(LIN) (M545-10-540-38500-01)	Attached sheet 5

L200/L200 SPORTERO/TRITON/STRADA/STRADA SPORTERO

<G. EXP/GCC/MMAL/NEW ZEALAND/SOUTH AFRICA/MEXICO>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2007 L200/L200 SPORTERO/TRITON/STRAD A/STRADA SPORTERO Workshop Manual (G. EXP/GCC)	PWTE0603R-1(English) PWTS0604R-1(Spanish)	Code No.U1570 No-Bus activity error for LIN  (M545-10-400-03801-01)	Attached sheet 4
2007 TRITON Workshop Manual (MMAL)	MMAL:MR936105	Code No.U1570 No-Bus activity error for LIN (M545-10-400-02701-01) 	
2008 L200/L200 SPORTERO/TRITON/STRAD A/STRADA SPORTERO Workshop Manual (G. EXP, GCC)	PWTE0703R(English) PWTS0704R(Spanish)	Code No.U1570 No-Bus activity error for LIN  (M545-10-400-03801-01)	
2008 TRITON Workshop Manual (MMAL/NEW ZEALAND/ SOUTH AFRICA)	MMAL:MR936232 MMNZ:DRAFT SOUTH AFRICA:DRAFT	Code No.U1570 No-Bus activity error for LIN (M545-10-400-05000-01) 	

2009 L200/L200 SPORTERO/TRITON/STRAD A/STRADA SPORTERO Workshop Manual (G. EXP/GCC/MEXICO)	PWTE0806R(English) PWTS0807R(Spanish) MEXICO:DRAFT	Code No.U1570 No-Bus activity error for LIN <vehicles for General Export and GCC> (M545-10-540-02800-01) Code No.U1570 No-Bus activity error for LIN <vehicles for Mexico> (M545-10-540-03900-01)	
2009 TRITON Workshop Manual (MMAL/NEW ZEALAND)	MMAL:MR936476 MMNZ:DRAFT	Code No.U1570 No-Bus activity error for LIN (M545-10-540-05100-01)	
2009 TRITON+3.5L Workshop Manual (MMAL/NEW ZEALAND)		Code No.U1570 No-Bus activity error for LIN (M545-10-540-16900-01)	
2010 L200/L200 SPORTERO/TRITON/STRAD A/STRADA SPORTERO Workshop Manual (G. EXP/GCC/MEXICO)	PWTE0903R(Eng) PWTS0904R(Spa) MEXICO:DRAFT	Code No.U1570 No-Bus activity error for LIN <vehicles for General Export and GCC> (M545-10-540-19200-01) Code No.U1570 No-Bus activity error for LIN <vehicles for Mexico> (M545-10-540-20000-01)	
2010 TRITON Workshop Manual (MMAL/NEW ZEALAND)	MMAL:DRAFT NZ:DRAFT	Code No.U1570 No-Bus activity error for LIN (M545-10-540-27700-01)	
2011 L200/L200 SPORTERO/TRITON/STRAD A/STRADA SPORTERO Workshop Manual (G. EXP/GCC/MEXICO)	PWTE1002R(Eng) PWTS1003R(Spa) MEXICO:DRAFT	Code No.U1570 No-Bus activity error for LIN <vehicles for General Export and GCC> (M545-10-540-28800-01) Code No.U1570 No-Bus activity error for LIN <vehicles for Mexico> (M545-10-540-29900-01)	

<THAILAND>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2008 TRITON Workshop Manual	DRAFT	Code No.U1570 No-Bus activity error for LIN (M548-51-030-01300-01) 	Attached sheet 4
2009 TRITON Workshop Manual			
2010 TRITON Workshop Manual		Code No.U1570 No-Bus activity error for LIN (M545-10-540-21100-01)	

<EU/RUSSIA>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2007.5 L200 Workshop Manual (EU)	CCRE07E2-CD(English) CCRS07E2-CD(Spanish) CCRF07E2-CD(French) CCRG07E2-CD(German) RUSSIA:N/A	Code No.U1570 No-Bus activity error for LIN (M545-10-400-01600-01) 	Attached sheet 4
2009 L200 Workshop Manual (EU/RUSSIA)	CCRE09E1-CD(English) CCRS09E1-CD(Spanish) CCRF09E1-CD(French) CCRG09E1-CD(German) CCRI09E1-CD(Italy) RUSSIA:N/A	Code No.U1570 No-Bus activity error for LIN (M545-10-540-13600-01)	

2010 L200 Workshop Manual (EU/RUSSIA)	CCRE10E1-CD(English) CCRS10E1-CD(Spanish) CCRF10E1-CD(French) CCRG10E1-CD(German) CCRI10E1-CD(Italy) RUSSIA:N/A	Code No.U1570 No-Bus activity error for LIN (M545-10-540-22200-01)	
2011 L200 Workshop Manual (EU/RUSSIA)	CCRE11E1-CD(English) CCRS11E1-CD(Spanish) CCRF11E1-CD(French) CCRG11E1-CD(German) CCRI11E1-CD(Italy) RUSSIA:N/A	Code No.U1570 No-Bus activity error for LIN (M545-10-540-33000-01)	
2012 L200 Workshop Manual (EU/RUSSIA)	CCRE12E1-CD(English) CCRS12E1-CD(Spanish) CCRF12E1-CD(French) CCRG12E1-CD(German) CCRI12E1-CD(Italy) RUSSIA:N/A	Code No.U1570 No-Bus activity error for LIN (M545-10-540-39600-01)	

PAJERO SPORT/NATIVA/MONTERO SPORT

<G. EXP/THAILAND/ARGENTINA/BRAZIL/SOUTH AFRICA/

RUSSIA/MEXICO/GCC/MMAL/NEW ZEALAND/THAILAND>

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2009 PAJERO SPORT/ NATIVA/MONTERO SPORT Workshop Manual (G. EXP/THAILAND/ARGEN TINA/BRAZIL/SOUTH AFRICA/RUSSIA)	PWJE0808R PWJS0809R THAILAND/ARGENTINA/B RAZIL/SOUTH AFRICA:DRAFT RUSSIA:N/A	Code No.U1570 No-Bus activity error for LIN <Except vehicles for Russia> (M545-10-540-10300-01) Code No.U1570 No-Bus activity error for LIN <Vehicles for Russia> (M545-10-540-11400-01)	Attached sheet 4
2009 PAJERO SPORT/ NATIVA/MONTERO SPORT Workshop Manual (G. EXP/THAILAND/ARGEN TINA/BRAZIL/SOUTH AFRICA/RUSSIA/MEXICO/ GCC)	PWJE0808R-1(English) PWJS0809R-1(Spanish) THAILAND/ARGENTINA/B RAZIL/SOUTH AFRICA/MEXICO:DRAFT RUSSIA:N/A	Code No.U1570 No-Bus activity error for LIN <Except vehicles for Russia and Mexico> (M545-10-540-14700-01) Code No.U1570 No-Bus activity error for LIN <Vehicles for Russia and Mexico > (M545-10-540-15800-01)	
2009 PAJERO SPORT/ NATIVA/MONTERO SPORT Workshop Manual (G. EXP/THAILAND/ARGEN TINA/BRAZIL/SOUTH AFRICA/RUSSIA/MEXICO/ GCC/MMAL/NEW ZEALAND)	PWJE0808R-2(English) PWJS0809R-2(Spanish) THAILAND/ARGENTINA/B RAZIL/SOUTH AFRICA/MEXICO:DRAFT RUSSIA:N/A MMAL/MMNZ:DRAFT		
2010 PAJERO SPORT/ NATIVA/MONTERO SPORT/CHALLENGER Workshop Manual (G. EXP/THAILAND/ARGEN TINA/BRAZIL/SOUTH AFRICA/RUSSIA/MEXICO/ GCC/MMAL/NEW ZEALAND)	PWJE0910R(English) PWJS0911R(Spanish) THAILAND/ARGENTINA/B RAZIL/SOUTH AFRICA/MEXICO:DRAFT RUSSIA:N/A MMAL/MMNZ:DRAFT	Code No.U1570 No-Bus activity error for LIN <Except vehicles for Russia, Mexico, Thailand, Australia, New Zealand> (M545-10-540-26600-01) Code No.U1570 No-Bus activity error for LIN <Vehicles for Thailand, Australia and New Zealand> (M545-10-540-25500-01) Code No.U1570 No-Bus activity error for LIN <Vehicles for Russia and Mexico> (M545-10-540-24400-01)	

2011 PAJERO SPORT/ NATIVA/MONTERO SPORT/CHALLENGER Workshop Manual (G. EXP/THAILAND/ARGEN TINA/BRAZIL/SOUTH AFRICA/RUSSIA/MEXICO/ GCC/MMAL/NEW ZEALAND)	PWJE1004R(English) PWJS1005R(Spanish) THAILAND/ARGENTINA/B RAZIL/SOUTH AFRICA/MEXICO:DRAFT RUSSIA:N/A MMAL/MMNZ:DRAFT	Code No.U1570 No-Bus activity error for LIN <Except vehicles for Russia, Mexico, Australia, New Zealand> (M545-10-540-30700-01) Code No.U1570 No-Bus activity error for LIN <Vehicles for Australia and New Zealand> (M545-10-540-31800-01) Code No.U1570 No-Bus activity error for LIN <Vehicles for Russia and Mexico> (M545-10-540-32900-01)	Attached sheet 4
2011 PAJERO SPORT Workshop Manual (THAILAND)	N/A	Code No.U1570 No-Bus activity error for LIN (M545-10-540-35200-01) 	

ZINGER

<CMC (TAIWAN) >

Applicable manual	Pub. No.	Applicable title (INFO-ID)	Contents
2006 ZINGER Workshop Manual	DRAFT 	Code No.U1570 No-Bus activity error(LIN) (M545-10-300-01300-01)	Attached sheet 4

DIAGNOSIS CODE NO.U1515

<Correct>

TROUBLE JUDGMENT
The ETACS-ECU will store diagnosis code No. U1515 when no communication has been carried out for more than a certain period after it received last valid data.

<Incorrect>

~~**TROUBLE JUDGMENT**
The ETACS-ECU will set diagnosis code No. U1515 when no communication has been carried out for more than a certain period after the slave task received last valid data.~~

DIAGNOSIS CODE NO.U1570

<Correct>

TROUBLE JUDGMENT
The ETACS-ECU will store diagnosis code No. U1570 when no communication has been carried out for more than a certain period after it received last valid data.

<Incorrect>

~~**TROUBLE JUDGEMENT**
The ETACS-ECU will set diagnosis code No. U1570 when no communication has been carried out for more than a certain period after the slave task received last valid data.~~