



SERVICE BULLETIN

GLOBAL AFTER SALES OFFICE, MITSUBISHI MOTORS CORPORATION

PURPOSE : Error Correction	ISSUE NO. : MSB-17EXML11-501	DATE : 2017-02-16
SUBJECT : Corrections of the error in writing of the cylindricity of 4B1 and 4J1 engines		<DESTINATION/MODEL> As shown below :
GROUP : Gr:11(Engine)		<M/Y> ALL
		All models with 4B1 and 4J1 engines

1. Description :

For the information about the correction of mention of an applied service manual, please refer to the information of "About the details"

2. About the details :

For overseas market

MMNA/USTP:

Correct: 0.015 mm(0.0059 inch) (The difference between the maximum diameter and the minimum diameter)

Incorrect: 0.15 mm(0.006 inch)

Except for MMNA:

(EU/RUSSIA/MEXICO/HONG KONG/KOREA/TAIWAN/CHINA/THAILAND/BRAZIL/INDONESIA

G. EXP/GCC/MMAL/NZ/ENGLAND/ISRAEL/BRUNEI/SINGAPORE/MALAYSIA/BRAZIL/SOUTH AFRICA/ ARGENTINA/INDIA

Correct: 0.015 mm(The difference between the maximum diameter and the minimum diameter)

Incorrect: 0.15 mm

※The related models : All models having 4B1 and 4J1 engines are applicable for this service bulletin