

PURPOSE : INFORMATION	ISSUE NO. : MSB-07E42-012	DATE : 2007-11-05
SUBJECT : HOOD WEATHERSTRIP AND HOOD WEATHERSTRIP FRONT	<div> <div><MODEL></div> <div>(EUR)</div> <div>OUTLANDER</div> <div>(GS45X)(CW0W)</div> </div> <div> <div><M/Y></div> <div>07, 08</div> </div>	
GROUP : BODY		

1. Description:

In order to improve the productivity, the hood weatherstrip and the hood weatherstrip front are modified. This Service Bulletin contains the following changes.

- The number of the clips, which fix the hood weatherstrip, is changed from 7 to 5.
- The length of the hood weatherstrip front is changed from 698 mm to 437 mm.
- The number of the clips, which fix the hood weatherstrip front, is changed from 6 to 4.

2. Applicable Manuals:

Manual	Pub. No.	Title (Info-ID)	Attachment
2007 OUTLANDER Workshop Manual	CGXE07E1-CD (English) CGXS07E1-CD (Spanish) CGXF07E1-CD (French) CGXG07E1-CD (German)	Hood Removal and Installation (M421-00-161-20700-01)	Attachment 1
2008 OUTLANDER Workshop Manual	CGXE08E1-CD (English) CGXS08E1-CD (Spanish) CGXF08E1-CD (French) CGXG08E1-CD (German)		

3. Interchangeability:

Interchangeable

4. Effective Date:

Hood weatherstrip: From the vehicles produced on the end of May 2007
Hood weatherstrip front: From the vehicles produced on the middle of November 2007

BODY
HOOD

42A-5

HOOD

REMOVAL AND INSTALLATION


M1421001601207

Post-installation operation


- Clearance check around the hood (Refer to P.42A-4.)
- Adjustment of the hood level and hood striker engagement (Refer to P.42A-4.)
- Adjustment of hood height (Refer to P.42A-4.)

<Added>

NOTE: Install the left end clip of hood weatherstrip front to left end attaching hole of hood weatherstrip front on hood side.



AC605070AC



AC605071AD